

Product: Dsp.NetPlus	Part No.: 2003	Version: V1.040
Date: 22nd Feb 2011	Main purpose: Improved protection, Alarms	
Features added: V1.020: <ul style="list-style-type: none"><input type="checkbox"/> Added current logging V1.040: <ul style="list-style-type: none"><input type="checkbox"/> Alarms feature<input type="checkbox"/> Improved communications performance in very large networks<input type="checkbox"/> Enhanced Power Supply Protection<input type="checkbox"/> Improved overcurrent protection at low temperatures<input type="checkbox"/> Greater sensitivity of protection indication		
Defects corrected: V1.020: <ul style="list-style-type: none"><input type="checkbox"/> The Model Name could become damaged when using version xxx4 of Flash memory V1.040: <ul style="list-style-type: none"><input type="checkbox"/> -		
Installation notes: <ul style="list-style-type: none"><input type="checkbox"/> Update to PodWare V5.44.0 or later on your computer<input type="checkbox"/> Copy the file DspNetPlus_2003V****.dfw to a known location on your computer<input type="checkbox"/> Start the PodWare application<input type="checkbox"/> Go On-Line to each device requiring an update, and launch the control panel for it<input type="checkbox"/> In the Device menu, select Update Firmware, then follow the instructions<input type="checkbox"/> Take great care not to disturb the device while it is reprogramming firmware since this could otherwise render the device inoperative		